

Misrepresentation of Intertek Certified Product Labels / Fausse représentation des étiquettes de produits certifiés Intertek

Various Fire Rated Door labels

Notification Type:	Misuse of Certification Mark / Mauvaise utilisation des marques de certification
Certification Type:	Not Intertek Certified

Notification

Intertek notifies public that we have been notified by the applicant that the labels identified below have been misrepresented as Intertek Certified.

Company Identification

Al Ghamdi Wood Industries Company

Product Identification

A misrepresentation of certified product labels. Al Ghamdi Wood Industries Company Ltd. for the following WH labeled product labels:

Listed 20 Mins Fire Rated Door (300) labels 003101 to 003400 - No Control number - see black label page 2
Listed Fire Door Rating: 1/2 hour (84) Labels 1018-1101 - No Control number - see green label page 2
Listed Fire Door 3/4 hour Rating (26) 001195 to 001200, 001249 to 001266 & 001268 to 001269 - No Control number - see darker green label page 2
Listed Fire Door 1 hour Rating (10) 001976, 001977, 002028 to 002035 - No Control number - see blue label page 2
Listed Fire Door 1-1/2 hour Rating (15) 001267 to 001276, 001280 to 001284- No Control number - see red label page 2

Hazard Involved

Not Intertek Certified

What To Do

Use should be immediately discontinued and return to the point of purchase and the labels should be removed and returned to Intertek.

Published: October 17, 2025
Revised:

Public Notice ID: 2025-98
Page 2 of 2

Photos and Images

